	Risk Assess	ment		
Risk Assessment for the activity of	Lab 1012/1017 Quantum Control expe	eriments	Date	28 Nov 2025
Unit/Faculty/Directorate	School of Physics & Astronomy	Assessor	Tim F	reegarde
Line Manager/Supervisor	Tim Freegarde	Signed off	liu	n (regya)

Version: 2.3/2017

Emergency, Safety & Health Telephone Numbers

from:	internal phone	external phone incl. cellphone	availability
Fire / Police / Ambulance	91-999	999 or 112	24 hours
Police – non-emergency		101	
First Aiders: Damon Grimsey	2-2040	023 8059 2040	Main Workshop (room 1005)
Kath Leblanc	2-2106	023 8059 2106	Teaching Lab (room 3040)
Sanja Barkovic	2-2065	023 8059 2065	Teaching Lab (room 3087)
University security – all emergencies	2-3311	023 8059 2311	24 hours
University security – non-emergency	2-2811	023 5055 8477	
Highfield health emergency		023 8055 8577	
Highfield health reception	2-5545	023 8055 0050	
University health service reception		023 8055 7531	
Building emergencies (electricity, gas, water etc.)	2-7474	023 8059 7474	Mon – Fri, 8am – 4pm
Building emergencies (electricity, gas, water etc.)	2-2811	023 5055 8477	Outside above hours
Nightline	2-5236	023 8059 5236	Term-time, 8pm – 8am
Student Life		023 8059 8180	24 hours
University switchboard	0	023 8059 5000	Mon – Fri, 8.30am – 5pm

Please report all accidents or incidents to

		internal phone	external phone incl. cellphone	email
Supervisor	Tim Freegarde	2-2347	023 8059 2347 / 07766 914346	timf@soton.ac.uk
School Safety Coordinator	Justin Harris	2-3936	023 8059 3936	j.p.harris@soton.ac.uk
Head of School	Seb Hoenig			hodphys@soton.ac.uk

and submit a report online via https://www.southampton.ac.uk/healthandsafety/incident-report.page

PART A										
(1) Risk identi	fication		(2)	Risk	ass	essment	(3)	Ris	k m	anagement
Hazard	Potential Consequences	Who might be harmed (user; those	Inh	eren	t	Control measures (use the risk hierarchy)	Re	sidu	al	Further controls (use the risk hierarchy)
		nearby; those in the vicinity; members of the public)	Likelihood	Impact	Score		Likelihood	Impact	Score	
General laboratory hazards	Risk of tripping, burns, electrocution	Users and those nearby or in the vicinity	3	2	6	 Laboratory should be kept reasonably tidy. Trailing leads should be avoided or covered securely to avoid tripping. Unused cardboard boxes etc. should not be stored in lab. No power sockets or mains electrical items should be powered whilst at floor level in case of flooding. Hotplates should be covered in use with signage to warn others of hot surfaces. Lone laboratory users should avoid potentially hazardous work, and if unavoidable should notify colleagues and laboratory manager. 	1	1	1	

Alignment and	Corneal and skin exposure:	Users and those	4	5	20	Beams should be confined to	1	5	5	Alignment should as far as
use of high-	burns and corneal damage	nearby.				fibres when possible.				possible be done at low
power mid-IR	potentially resulting in					Open fibres and connectors should				power.
fibre laser	partial to complete					be securely blocked by caps or				 Free-space sections should be
	1 .					beam guards.				fully enclosed in regular
amplifier	blindness from exposure to					Open or damaged fibres and				operation, and opened only
1560nm, 15W	direct beam or diffuse					connectors should be treated as				for alignment.
	reflections.					potentially hazardous within 1 m.				J
						Free-space beams should be				
						restricted to a plane securely				
						bounded by solid beam-guards.				
						Unusual beam paths should be				
						securely blocked by solid beam-				
						guards.				
						 Beam paths not requiring frequent 				
						adjustment should be fully				
						enclosed.				
						Optics and hardware should be				
						secure during alignment.				
						Suitable protective eyewear shall				
						be worn during beam alignment				
						and by all temporary lab visitors				
						while free-space beams are				
						exposed; note that eyewear may				
						be insufficient to block high				
						intensity beams.				
						 Rings, wristwatches and reflective 				
						jewellery on hands and arms shall				
						be removed before carrying out				
						optical alignment.				
						Lasers shall be interlocked to the				
						lab door through their controllers				
						or via a mechanical shutter close				
						to the beam source. A clear				
						warning light above the door shall				
						indicate when the interlock is				
						engaged.				
						engagea.				

Alignmentand	Dating corned and skin	Users and those	1	1	20	Beams should be confined to	1	1	1	Version: 2.3/201
Alignment and	Retinal, corneal and skin		4	4	20	fibres when possible.	'	4	4	Alignment should as far as
use of high-	exposure: burns and mild	nearby.								possible be done at low
power near-IR	to very severe retinal					Open fibres and connectors should be securely blocked by some or				power.
SHG sources	damage potentially					be securely blocked by caps or				
	resulting in partial to					beam guards.				
780nm, <10W	complete blindness from					Open or damaged fibres and				
	exposure to direct beam or					connectors should be treated as				
	diffuse reflections.					potentially hazardous within 1 m.				
	directions.					 Free-space beams should be 				
						restricted to a plane securely				
						bounded by solid beam-guards.				
						 Unusual beam paths should be 				
						securely blocked by solid beam-				
						guards.				
						 Beam paths not requiring frequent 				
						adjustment should be fully				
						enclosed.				
						 Optics and hardware should be 				
						secure during alignment.				
						 Suitable protective eyewear shall 				
						be worn during beam alignment				
						and by all temporary lab visitors				
						while free-space beams are				
						exposed; note that eyewear may				
						be insufficient to block high				
						intensity beams.				
						 Rings, wristwatches and reflective 				
						jewellery on hands and arms shall				
						be removed before carrying out				
						optical alignment.				
						 Lasers shall be interlocked to the 				
						lab door through their controllers				
						or via a mechanical shutter close				
						to the beam source. A clear				
						warning light above the door shall				
						indicate when the interlock is				
						engaged.				
		J		1		engageu.				

Alignment and	Retinal exposure: mild to	Users	4	3	12	Open fibres and connectors should	1	3	3	Alignment should as far as
_		OSEIS	"	, J	12	be securely blocked by caps or	•	,	3	=
use of near/mid-	very severe retinal damage					beam guards.				possible be done at low
IR diode and	potentially resulting in					 Open or damaged fibres and 				power.
fibre lasers and	partial to complete					connectors should be treated as				
SHG sources	blindness from direct beam									
	exposure.					potentially hazardous at close				
FP diode	Minor skin burns from					range.				
780 nm, 100 mW	direct exposure to focused					Free-space beams should be				
,	beam.					restricted to a plane securely				
Tapered amplifier	Deam.					bounded by solid beam-guards.				
780 nm, 80 mW						 Unusual beam paths should be 				
700, 00						securely blocked by solid beam-				
DBR diode						guards.				
780 nm, 200 mW						 Beam paths not requiring frequent 				
700 1111, 200 1111						adjustment should be fully				
Fibre laser						enclosed.				
1560 nm, 50 mW						 Optics and hardware should be 				
1300 1111, 30 11100						secure during alignment.				
						 The use of suitable protective 				
						eyewear is strongly advised and				
						encouraged, especially during				
						beam alignment and by all				
						temporary lab visitors while free-				
						space beams are exposed; visual				
						alignment without goggles should				
						be conducted with care.				
						 Rings, wristwatches and reflective 				
						jewellery on hands and arms shall				
						be removed before carrying out				
						optical alignment.				
						_				
						Lasers shall be interlocked to the lab door gither through their				
						lab door, either through their				
						controllers or via a mechanical				
						shutter close to the beam source.				
						A clear warning light above the lab				
						door shall indicate when the				
						interlock is engaged.				

PART A										,
(1) Risk identif	fication		(2)	Risk	ass	essment	(3)	Risl	c ma	anagement
Hazard	Potential	Who might be	Inh	eren	t		Res	sidu	Further controls (use	
	Consequences	harmed (user; those nearby; those in the vicinity; members of the public)	Likelihood	Impact	Score	Control measures (use the risk hierarchy)	Likelihood	Impact	Score	the risk hierarchy)
High voltage supplies to ion pumps, Pockels cells, and photomultipliers; mains supplies to general lab equipment.	Electric shock, electrical fire, electrical burns, paralysis, fire.	Users and those nearby.	4	5	20	 Electrical shielding and earthing of mains and high voltage supplies shall be intact and secure. Mains electrical equipment should be raised above the floor to avoid electrical hazards in case of spillage or flooding. Construction, repair and alteration of electrical items should be carried out or checked by competent persons. Mains apparatus shall be tested regularly by qualified persons. 	—	5	5	CO ₂ fire extinguishers, firstaid kits and trained firstaiders located within immediate vicinity of laboratory.

Electronic prototyping & assembly Contact of soldering iron with skin or flammables; electric shock; burns, paralysis, fire Users 3 4 12 • Devices should be disconnected from power supplies and high voltage/capacity capacitors discharged safely and shorted before working on them.	•
assembly electric shock; burns, paralysis, fire voltage/capacity capacitors discharged safely and shorted	
paralysis, fire discharged safely and shorted	
and the second s	
before working on them.	
High voltage circuitry should not	
be exposed unnecessarily.	
Components, cables and circuit	
boards should when possible be	
positioned securely for soldering	
and testing to minimize the	
chances of shocks and soldering	
iron burns.	
Exposed metalwork should be	
earthed during testing and	
operation for protection should	
high voltage wiring come loose.	
Testing should only be carried out	
by appropriately briefed or	
experienced personnel, and not	
while working alone.	
Mains, high voltage and high	
power devices should be checked	
after construction, servicing or	
modification by competent	
personnel before being connected	
to a supply.	

PART A										
(1) Risk identi	fication		(2)	Risk	asse	essment	(3)	Ris	k m	anagement
Hazard	Potential	Who might be	Inh	eren	t		Residual			Further controls (use
	Consequences	harmed (user; those nearby; those in the vicinity; members of the public)	Likelihood	Impact	Score	Control measures (use the risk hierarchy)	Likelihood	Impact	Score	the risk hierarchy)
Solvent storage and use Acetone Iso-Propyl Alcohol (IPA)	Spillage, skin exposure, ingestion: skin irritation, eye damage, poisoning, fire.	Users	3	4	12	 Solvents should be stored in appropriate containers at a low level to reduce the risk of breakages. Storage and distribution vessels should be no larger than required and appropriately labelled. The use of low flow-rate-outlet plastic bottles is advised to reduce the risk of spillage. Goggles and protective gloves should be worn to avoid eye/skin contact if otherwise likely. Glove compatibility should be checked before use. Inhalation should be avoided. 	1	3	3	

PART A										
(1) Risk identif	fication		(2)	Risk	ass	essment	(3) Risk management Residual Further controls (the risk hierarchy) 1 4 4 1 3 3			anagement
Hazard	Potential	Who might be	Inh	eren	t		Re	sidu	al	Further controls (use
	Consequences	harmed (user; those nearby; those in the vicinity; members of the public)	Likelihood	Impact	Score	Control measures (use the risk hierarchy)	Likelihood	Impact	Score	the risk hierarchy)
SAES Rubidium dispensers used in experimental chamber contain Zirconium and Rb Chromate	Inhalation or skin exposure: may cause irritation or cancer	Users and those nearby	2	4	8	 SAES dispensers are enclosed in metal boats which only expose carcinogens upon activation by heating to >400°C. Gloves should be worn when handling dispensers, which shall be activated only when enclosed and under vacuum. Dust inhalation shall be avoided on the rare occasions that the chambers are opened. 	1	4	4	
Solder, flux and inhalation fumes	Inhalation, irritation and poisoning	Users and those nearby	3	3	9	 Minimize inhalation of solder, flux and fumes when soldering For big jobs, use fume extraction apparatus Keep iron tips clean using foam pad dampened with water Use lead-free solder with lower-hazard flux whenever possible Follow guidance at https://sotonac.sharepoint.com/te ams/HealthSafetyRisk/SitePages/Soldering.aspx 	1	3	3	

(1) Risk ident	ification		(2)	Risk	asse	essment	(3)	the risk hierarchy)		
Hazard	Potential	Who might be		eren						Further controls (use
	Consequences	harmed (user; those nearby; those in the vicinity; members of the public)	Likelihood	Impact	Score	Control measures (use the risk hierarchy)	Likelihood	Impact	Score	the risk hierarchy)
High-pressure gas cylinders	Asphyxiation, explosion	Users and those nearby	3	4	12	 Use and manoeuvring by trained persons only Low output pressure (<2 bar) to be used Cylinders must be securely chained/strapped to wall or bench to avoid toppling No modifications should be made to cylinders or regulators unless by certified personnel Cylinders should be considered pressurized regardless of gauge indications Room must be well ventilated when venting gases to avoid asphyxiation risk Cylinders should be as small, and retained as briefly, as feasible to minimize explosion hazard in case of building fire. 	1	4	4	

PART A										
(1) Risk identification			(2) Risk assessment				(3) Risk management			
Hazard	Potential Consequences	Who might be harmed (user; those nearby; those in the vicinity;		eren	t	Control measures (use the risk hierarchy)		sidu	al	Further controls (use the risk hierarchy)
Oven 200°C	Burns	members of the public) Users	w Likeli	2 Impact	9 Score	 Users must be trained in use of oven Lab users should be made aware when oven is in use Oven should if possible not be left running overnight; if unavoidable for baking out, over-temperature safeguards should be set Users should wear appropriate gloves when removing hot or warm items, noting that they may remain hot for some time after the oven has been switched off No flammable objects or items likely to melt or produce noxious fumes should be present within the oven during operation. 	– Likeli	- Impact	1 Score	

PART B - Action Plan

Risk Assessment Action Plan

Part no.	Action to be taken, incl. Cost	By whom	Target date	Review date	Outcome at review date
Respo	Responsible manager's signature:			Respons	ible manager's signature:
Print	name:		Date:	Print nar	me: Date

Version: 2.3/2017

Revision record


Date	Document owner	email
03.04.24	Tim Freegarde	timf@soton.ac.uk

Please send all suggestions for revision to the current document owner.

Version	Date	Pages	Changes
1.0	03.04.24		
1.1	26.02.25	14	Revision record added
		16	Users updated
1.2	28.11.25	4-6	Full enclosure of beam paths added
		9	Soldering hazard mitigations revised
		16	Users updated

Assessment Guidance

1. Eliminate	Remove the hazard wherever possible which negates the need for further controls	If this is not possible then explain why	1
2. Substitute	Replace the hazard with one less hazardous	If not possible then explain why	2
3. Physical controls	Examples: enclosure, fume cupboard, glove box	Likely to still require admin controls as well	3
4. Admin controls	Examples: training, supervision, signage		4
5. Personal protection	Examples: respirators, safety specs, gloves	Last resort as it only protects the individual	5



Risk process

- 1. Identify the impact and likelihood using the tables above.
- 2. Identify the risk rating by multiplying the Impact by the likelihood using the coloured matrix.
- 3. If the risk is amber or red identify control measures to reduce the risk to as low as is reasonably practicable.
- 4. If the residual risk is green, additional controls are not necessary.
- If the residual risk is amber the activity can continue but you must identify and implement further controls to reduce the risk to as low as reasonably practicable.
- If the residual risk is red <u>do not continue with the activity</u> until additional controls have been implemented and the risk is reduced.
- 7. Control measures should follow the risk hierarchy, where appropriate as per the pyramid above.
- 8. The cost of implementing control measures can be taken into account but should be proportional to the risk i.e. a control to reduce low risk may not need to be carried out if the cost is high but a control to manage high risk means that even at high cost the control would be necessary.

Imp	act	Health & Safety
1	Trivial - insignificant	Very minor injuries e.g. slight bruising
2	Minor	Injuries or illness e.g. small cut or abrasion which require basic first aid treatment even in selfadministered.
3	Moderate	Injuries or illness e.g. strain or sprain requiring first aid or medical support.
4	Major	Injuries or illness e.g. broken bone requiring medical support >24 hours and time off work >4 weeks.
5	Severe - extremely significant	Fatality or multiple serious injuries or illness requiring hospital admission or significant time off work.

Likelihood	
1	Rare e.g. 1 in 100,000 chance or higher
2	Unlikely e.g. 1 in 10,000 chance or higher
3	Possible e.g. 1 in 1,000 chance or higher
4	Likely e.g. 1 in 100 chance or higher
5	Very Likely e.g. 1 in 10 chance or higher

Version: 2.3/2017

Declaration by users: I confirm that I have read this risk assessment, will implement the controls outlined herein, and will report to the responsible manager any incidents that occur or any shortcoming I find in this assessment.

Name

Signature

Date

Name	Signature	Date
Tim Freegarde	Tim Kregge	28 November 2025
Joel Abraham	T Start.	28 November 2025
Alfie Preston	A Preston	01 December 2025
Tommy Roe		28 November 2025
Rupayan Das		28 November 2025
Jack Saywell	78=	28 November 2025